

PLSS Monument Preservation Sheet

Township Range Section Meridian

BLM Point ID

U T 2 6 0 0 5 0 S 0 2 1 0 E 0 1 0 3 1 0 0

Date

04-06-2009

Meridian

Township

N
S

Range

E
W

Section

Corner

Salt Lake

Uintah

5

S

2

1

E

3

1

NW

NE

SE

SW

Contact's Name

John R. Slaugh

State

Utah

Contact's Phone

435-789-1365

N 1/4

E 1/4

S 1/4

W 1/4

License #

6028691

County

Uintah

WC

RC

MC

Other

Source Agency

Uintah County

PLSS Monument Coordinates

Datum

NGS National Spacial Reference System Adjustment

NAD 27

NAD 83

WGS 84

NAD 83
1986

NAD 83
1994 (OPUS)

NAD 83
2007

NAD 83
1994 (HARN)

Latitude (DMS)

Longitude (DMS)

N 4 0 - 1 9 - 5 5 . 1 5 1 3 0

W 1 0 9 - 3 6 - 4 0 . 0 5 6 0 8

Northing

Easting

7 2 9 5 2 1 5 . 1 8

2 1 6 6 9 6 4 . 7 8

Units

Survey Foot

International Foot

Meter

Coordinate Type

State Plane

UTM (Zone 12N)

Zone

Utah North

Utah central

Utah South

Vertical datum

NGVD 29

NAVD 88

Ellisode Height

M 5033.72

FT

Elevation

M 5091.49

FT

Monument and Markings

Type/Size

Stone

Pipe/Cap

Post

Other

Size

Size

Size

Size 3/4" rebar / 2.5" Cap

Material

Material




Material

Material Aluminum

Surveyor Seal

Section Location Diagram

Monument Inscription



Signature & Date

Description and Observation of Monument


2009 Uintah County Surveyor aluminum cap on 3/4" rebar with 3.5' Dia. x 1.5' high mound of stones around the cap.

Sketch/Rubbing or Attach Photo of GPS Station Occupied

Show rotation of stampings/markings relative to North and describe briefly

SURVEYOR'S NARRATIVE OF THE CORNER:

At the Angle Point we found a loosely set stone with AP chiseled on north face. Stone measures 24" x 14" x 14" (bottom 12" of stone leached of color from being below grade) and was surrounded by a mound of stones 42" in diameter by 18" high. We removed the set stone and replaced it with a 3/4" rebar fitted with a 2.5" 2009 Uintah County Surveyor Aluminum Cap, marked for the Angle Point. We placed the stone along the southern edge of the cap with markings to north and re-built the pile of stones around cap.



County Surveyor Aluminum Cap
on 3/4" Rebar